



JAMESTOWN S'KLALLAM TRIBE

1033 Old Blyn Highway, Sequim, WA 98382

360/683-1109

FAX 360/681-4643

7/29/15

To;
Marie Jennings, Manager
Drinking Water Unit
Environmental Protection Agency
1200 Sixth Avenue, Suite 900 - OWW 193
Seattle, WA 98101

I am writing in response to the letter sent on January 6th of this year. The Jamestown S'Klallam Tribe has determined which form of corrosion control will work best to remediate our elevated copper levels at the 7 Cedars Casino. We conducted tests for PH, Calcium, Alkalinity, and Conductivity. The "EPA Guidance Manual for Selecting Lead and Copper Control Strategies" indicates that our best course of action would be to use aeration to bring up the PH (6.8) and to use orthophosphate to limit the copper levels in the water.

Additionally we've taken steps to try and further curb any additional corrosion by installing backflow prevention assemblies at all the cross-connections for CO2. Presently we've been in contact with two firms to help investigate more thoroughly and design a system to meet our corrosion control needs.

Thank you for your time and patience in this matter,

Bill Laubner
Facilities manager
Work: 360-582-5785
Cell: 360-912-3396
blaubner@jamestowntribe.org

IJ/BL

Ilan Jones